

MAGILL SERVICES, INC.

268 Dresser Hill Road
Southbridge, MA 01550

Tel (843) 652-7000 or (603) 747-4111
www.magillservicesinc.com

LABORATORY REPORT

OLL 18030

Date: September 20, 2022

Test Report # 220957

BAINBRIDGE INTERNATIONAL, INC.

255 Revere Street
Canton, MA 02021

Subject: One (1) sample of material tested for **Flame Resistance** in accordance with **NFPA 701, Test Method 2.**

Identification: **PO# 17694 Prod. Code CG 20 Mil SF Lot # 94196-1**

Testing Completed: September 20, 2022

<u>TEST, UNIT OF MEASURE</u>	<u>RESULTS</u>	<u>REQUIREMENTS</u>
Flame Resistance		
(NFPA 701-Chapter 14) Test Method 2 - Fold		
After flame, seconds	0.0 0.0 0.0 0.0	
Average:	0.0	2.0 Maximum Individual
Char length, inches	10.2 17.7 19.3 11.7	
Average:	14.7	41.3 Maximum Individual
Dripping and flaming, seconds	0.4 0.0 0.3 0.5	
Average:	0.3	2.0 Maximum

The sample tested above **meets** the requirements outlined in Chapter 15 of NFPA 701 Test Method 2.

I certify that the above tests were performed under my supervision in accordance with the specification test requirements and that the reported test results are true, valid and applicable to the samples tested. I further certify that these samples are the only samples tested from the lot of components identified above.

Signed 
Edward L. Magill Jr.
President

This report is for the exclusive use of the client to whom it is addressed and its communication to any others or use of the name Magill Services, Inc. must receive our prior written approval. This report is applicable only to the sample or samples tested.